





DISPENSA TANDEM III



KESSEBÖHMER



<https://www.kesseboehmer.com/downloads/tandem>










DE Korrosionsprüfung nach DIN EN ISO 6270-2 **EN** Corrosion test according to DIN EN ISO 6270-2 **FR** Contrle de la corrosion selon DIN EN ISO 6270-2 **IT** Prova di corrosione secondo la norma DIN EN ISO 6270-2 **ES** Prueba de corrosión según DIN EN ISO 6270-2 **PT** Ensaio de corrosão conforme DIN EN ISO 6270-2 **FI** DIN EN ISO 6270-2 muk. korroositestaus **NO** Korrosionsprøving iht. DIN EN ISO 6270-2 **CS** Korozní zkouška dle DIN EN ISO 6270-2 **PL** Badanie odporności na korozję wg DIN EN ISO 6270-2

DISPENSA TANDEM III



1




W	FH	CH	CW	CD
450	1032	≥ 1100	412 - 418	≥ 500
450	1632	≥ 1700	412 - 418	≥ 500
500	1032	≥ 1100	462 - 468	≥ 500
500	1632	≥ 1700	462 - 468	≥ 500
600	1032	≥ 1100	562 - 568	≥ 500
600	1632	≥ 1700	562 - 568	≥ 500


DISPENSA TANDEM III




2




1x



1x






1x



4x






PZ2






DISPENSA TANDEM III



3







4







DISPENSA TANDEM III



5











6



DISPENSA TANDEM III




7






DISPENSA TANDEM III




8




1x






9



2x




4x




DISPENSA TANDEM III



10




1x



1x









1x



8x




PZ2




DISPENSA TANDEM III




11





1x



1x



1x



R




L

DISPENSA TANDEM III




12



450 / 500



12a
















600



12b

12a 450 / 500




















DISPENSA TANDEM III



12b


600




DISPENSA TANDEM III



13







14







DISPENSA TANDEM III



15




16




DISPENSA TANDEM III




i




1x






1x



4x



PZ2




	CH	A
	≥ 1100	1069
	≥ 1700	1669


DISPENSA TANDEM III



i







2x




4x



PZ2



W	B
450	W-50+X
500	W-50+X
600	W-50+X




CH	C
≥ 1100	1065+Y
≥ 1700	1665+Y


DISPENSA TANDEM III




i




1x







1x




8x



PZ2






	CH	D
	≥ 1100	1059
	≥ 1700	1659





17

Tandem Depot



DISPENSA TANDEM III



18

